

## 曜凌光電股份有限公司 Raystar Optronics, Inc.

42881台中市大雅區科雅路25號5樓 5F, No. 25, Keya Road, Daya Dist., Taichung City 42881, Taiwan T:+886-4-2565-0761 | F:+886-4-2565-0760 sales@raystar-optronics.com | www.raystar-optronics.com

Issue Date: November 10, 2022

## **NotificationSubject: NEOTEC IC EOL**

■ Description: The IC supplier-NEOTEC announced discontinuing STN IC NT7065B

■ Effected model:

Effected Parts	Only the suffix JS/CS/ES series are affected:
	RC1202A \ RC1602A \ RC1602B \ RC1602C \ RC1602D
	RC1602B1 \ RC1602E \ RC1602F \ RC1602G \ RC1602G1
	RC1602H \ RC1602I \ RC1602M \ RC1602O \ RC1604A
	RC1604B \ RDC0014 \ RDC0015

## ■ Recommend Action

Raystar has enough inventroy for at least 6 months, and is testing and planning to adapt to alt ernative IC ST7065C for further production.

Raystar appreciated your support in our products and we will continue to do our best to support and work with you. If there have any further questions, please feel free to contact with your service sales window.

Best Regards

RAYSTAR OPTRONICS, INC.