

曜 凌 光 電 股 份 有 限 公 司 Raystar Optronics, Inc.

42881台中市大雅區科雅路25號5樓 5F, No. 25, Keya Road, Daya Dist., Taichung City 42881, Taiwan T:+886-4-2565-0761 | F:+886-4-2565-0760 sales@raystar-optronics.com | www.raystar-optronics.com

Issue Date: August 29, 2022


Product Change Notification

- Description: In order to improve production efficiency and yield, and more in line with the in-house process, the following backlight optimization changes will be made.
- Description of change: The width of the backlight protruding metal frame is increased from 30mm to 31.2mm

■ Effected model:

| | RC1604A-BIW-xxx series | RC1604A1-BLW-xxx series |
|----------------|-------------------------|-------------------------|
| Effected Parts | RC1604A2-FHW-xxx series | RC1604A2-BLW-xxx series |
| | RC1604A-BLW-xxx series | RC1604A-FHW-xxx series |
| | RC1604A-GHW-xxx series | RC1604A-TIW-xxx series |
| | RC1604A-TLW-xxx series | RC1604A-YHW-xxx series |
| | RC1604A-BIW-JWV-000 | RC1604A-BIW-JWV-001 |
| | RC1604A-YKY-JSXE-000 | |

■ Module Drawing Comparison



Action plan

For the corresponding full part numbers, please contact your sales window or email to sales@raystar-optronics.com. Thank you for your understanding and support.

Best Regards

RAYSTAR OPTRONICS, INC.