

Issue Date: October 19, 2022







Product Change Notification


- Description: In order to improve production efficiency and yield, and more in line with the in-house process, the following metal frame and PCB optimization changes will be made.
- Description of change:
 - 1 · Adding positioning column and the side seal opening on the metal frame.
 - 2 · The shape of the positioning holes of the metal frame on the PCB are changed from square to round, and the positions of some components are changed.

■ Effected model:

Effected Parts	RC4004A Series
----------------	----------------

■ Module Drawing Comparison

Before Change	After Change
	
The metal frame increases the positioning column and the side seal opening	
	
The positioning holes of the metal frame on the PCB are changed from square to round	
	
Changes in the position of some components on the PCB	



曜凌光電股份有限公司
Raystar Optronics, Inc.

42881台中市大雅區科雅路25號5樓
5F, No. 25, Keya Road, Daya Dist., Taichung City 42881, Taiwan
T : +886-4-2565-0761 | F : +886-4-2565-0760
sales@raystar-optronics.com | www.raystar-optronics.com

■ Action plan

For the corresponding full part numbers, please contact your sales window or email to sales@raystar-optronics.com. Thank you for your understanding and support.

Best Regards


RAYSTAR OPTRONICS, INC.