

曜凌光電股份有限公司 Raystar Optronics, Inc.

42881台中市大雅區料雅路25號5樓 5F, No. 25, Keya Road, Daya Dist., Taichung City 42881, Taiwan T:+886-4-2565-0761 | F:+886-4-2565-0760 , sales@raystar-optronics.com | www.raystar-optronics.com

Issue Date: 07 August, 2023

NotificationSubject: STN LCD POLARIZER EOL

- Description: Optimax, Nitto and SAPO suppliers announced EOL of polarizers used in STN LCD modules
- Effected model:

Effected Parts	Various	
----------------	---------	--

Recommend Action

Due to the discontinued polarizer is important material in the LCD display module.

Raystar will select the alternative polarizer similar with the original one as much as possible to minimize the effect to display performance.

The relevant Last buy will be limited by the information provided by each glass factory, please contact with your responsible sales person for details.

Raystar appreciated your continued support. We will continue to devote all our best to support and work with you. If there have any further questions, please feel free to contact with your service sales window.

Raystar appreciated your continued support. We will continue to devote all our best to support and work with you. If there have any further questions, please feel free to contact with your service sales window.

Best Regards

RAYSTAR OPTRONICS, INC.